## INVOICE

**Robert Harrison** 

fireplace-repair@domain.com (XXX)-555-XXXX

Bill To: <b>John Smith</b> 123 Main Street, Anytown, CA 90001 john.smith@domain.com (XXX)-555-XXXX	Invoice		#INV-000101
	Issued Date:		02/20/2025
	Balance Due:		\$765
Services	QTY	Price	Total
Thorough inspection of the fireplace structure and components.	1	\$100	\$100
Cleaning of chimney to remove soot, creosote, and debris.	1	\$150	\$150
Repair or replacement of the fireplace damper.	1	\$120	\$120
Installation of a new flue liner for safety and efficiency.	1	\$200	\$200
Repair cracks or damage within the firebox area.	1	\$180	\$180

Subtotal:	\$750
Tax:	\$15
Total:	\$765

## Terms & Conditions:

Payment Due Upon Receipt. Please choose one of the following payment methods: Check: Robert Harrison 123 Main Street, Anytown, CA 90001 Zelle: Robert Harrison (XXX)-555-XXXX/robert.harrison@domain.com Venmo: @Robert-Harrison